



# RO13310 Arcbuster welding coverall



## TICKING ALL BOXES

**PROTECTION LEVEL:**  
**ARC 2**

**18.0 cal/m<sup>2</sup>**

Above shown is the ATPV value.

## EN SAFETY STANDARDS



EN 13688:2013



EN ISO 11611:2015  
Class 2 A1 A2



EN ISO 11612:2015  
A1+A2 B1 C2 D0 E3 F1



EN 61482-2:2020  
APC 1 (4 kA)  
ELIM = 16,8 cal/m<sup>2</sup>  
ATPV = 18,0 cal/m<sup>2</sup>

## QUICK DETAIL OVERVIEW

### Available colours

■ Navy ■ Orange

### Product code

RO13310

### Sizing

UK36 - UK64

### Fabric weight

Coverall: 440 g/m<sup>2</sup>

### Inside leg length

Short: 29"  
Regular: 31"  
Tall: 33" (standard size)

This garment is mostly used in > Welding



# RO13310 Arcbuster welding coverall

## FEATURES & BENEFITS

- Concealed heavy-duty jeans closure > Sturdy and out of sight
- 2 internal chest pockets > Safely tuck away your goods
- 2 back pockets with flap > Ambidextrous rear storage space
- 2 side pockets > Ambidextrous storage space
- 1 tool pocket > Extra space for tools
- Internal knee pockets > Stow away your knee pockets internally

## KEY FEATURES



Treated fabric



Visible safety standards



Internal knee pad pockets



Triple stitched

## Related products



**RO8008 - ROOTS knee pads**  
A pair of foam knee pads.

## FABRIC INFORMATION

### Fabric composition

FLC440 - 99% cotton / 1% antistatic

### Fabric weight

440 g/m<sup>2</sup>

### FR Fabric Type

Treated

### Additional certification



1. Oeko-Tex Standard 100
2. AS/NZ 4399:1996 Sun protective clothing UPF 50+ (Excellent Protection)

Please visit [www.roots-original.com/certificates](http://www.roots-original.com/certificates) to download all relevant certificates.

### Logo

Certified for logo applications

## Product care instructions

To preserve the fabrics strength and protective capacity, we strongly advice to follow our detailed care instructions.

1. Always launder with coverall zippers closed.
2. Remove all tools from pockets
3. Rinse properly after wash.
4. Never wash flame retardant clothing with detergents containing bleach.
5. After washing, tumble dry at 50°C to avoid excessive shrinkage.
6. Do not iron directly over heat seal logos.



Whenever in doubt or in need of advice, ask your dry cleaner or contact us. We are here to help or visit [www.roots-original.com/product-care](http://www.roots-original.com/product-care)



## YOUR ARC FLASH PROTECTION SPECIALISTS

Get in contact, we'd love to help you!

Give us a call on +31 (0)10 2955 955 or drop us a message at: [info@roots-original.com](mailto:info@roots-original.com)