ROOTS CARE LABELING SYSTEM



WASHING		3 BLEACHING		 DRYING		IRONING		P	= PROF. CLEANING	
/	Normal process	3	Any bleach allowed	G	Tumble drying possible	9	Max. 200°C	@	Professional dry-cleaning in tertrachlorethene	
0	Gentle proces				r	•	Max. 150°C			
*	Normal process	4	Only oxygen/ Non-chlorine bleach allowed	Н	Tumble drying possible - Low temperature	• /	Max. 110°C	С	Gentle process	
+	Gentle proces	7	Do not bleach	J	Do not tumble dry	<	Do not iron	?	Professional dry- cleaning in hydrocarbons	
\$	Normal process					- 1				
%	Gentle proces	_						В	Gentle process	
!	Normal process							A	Do not dry-clean	
11	Gentle proces							D	Professional wet- cleaning	
#	Very gentle process	-						E	-	
1	Gentle proces							F	Very gentle process	
2	Do not wash	-						M	Do not wet-clean	